



July 2011

URGENT SAFETY RECALL

CLUB CAR MODEL YEAR 2011 DS GOLF CARS, HOSPITALITY AND UTILITY & TRANSPORT VEHICLES

Dear Club Car Customer:

Club Car, LLC, in cooperation with the U. S. Consumer Product Safety Commission, is notifying all owners and operators of 2011 model year DS golf cars and small wheeled utility products of a risk of brake pedal mounting block breakage in certain units due to improper processing of the brake pedal mounting blocks. This problem, if not corrected, could present a loss of braking ability, posing a crash hazard. Club Car is recalling brake blocks with certain manufacturing date codes in 2011 model year vehicles.

Club Car, in conjunction with its dealers and distributors, has initiated a field campaign to replace the brake pedal mounting blocks in the affected vehicles. The replacement will be done free of charge.

This letter is to provide the information you will need to identify the affected vehicles and the actions you should take to ensure that brake pedal assembly in your vehicle is inspected expeditiously.

Which vehicles are affected?

- Certain 2011 DS model golf cars, hospitality, utility & transport and rough terrain vehicles. A full listing of affected models and serial numbers is attached. Precedent model golf cars and all wheel drive products **are not** affected.

What is the problem?

- Brake pedal mounting blocks may break during operation.
- This condition, if uncorrected, may lead to loss of brakes on the vehicle.

Our records indicate that you are the current owner of a 2011 DS model golf car, hospitality, or utility and transport vehicle or vehicles. If you are no longer in possession of the vehicle(s), please contact us at 1-800-227-0739 extension 3580 with any information you might have concerning their current location.

Immediate actions to be taken for affected vehicles:

STEP 1:

- Determine whether the serial number(s) of your 2011 DS model golf car, hospitality, or utility & transport vehicle or vehicles are on the list of potentially affected vehicles in Table 1 (see serial number decal example at right). The serial number is located on a decal just above and to the right of the accelerator pedal. The serial number consists of a two-letter prefix followed by a ten-digit number. The prefix and number must both match the model listings shown in Table 1 for your vehicle to be affected.



STEP 2

- If your vehicle is included in Table 1, **STOP USING THE VEHICLE** and immediately contact your authorized Club Car dealer or call Club Car at **1-800-227-0739, ext. 3580** between 8 a.m. and 5 p.m. ET to arrange for an repair of your vehicle(s).

We have initiated these steps out of our concern for safety and continued satisfaction with Club Car products and regret any inconvenience this may cause. Your cooperation and patience in dealing with this important issue is appreciated.

TABLE 1

Golf Cars and Hospitality Vehicles



**DS Electric Golf Car
IQ System / PowerDrive System 48
AQ
1137-227664 to 1139-232150**



**DS Gas Golf Car
AG
1137-227689 to 1139-233275**



**Café Express,
AF
1137-228254 to 1139-231797**

Transportation and Utility Vehicles



**Villager 4
TG
1137-228179 to 1137-228179**



**Villager 6, Villager 6 Plus
KG/QS
1137-227397 to 1139-232629**



**Villager 8
MG/QE
1137-228251 to 1139-232424**



**Carryall 232
XL/XM
1137-227646 to 1138-2229710**



**TransPorter 4
JS/JT
1137-228594 to 1139-231845**



**TransPorter 6
JQ
1137-227511 to 1139-232011**



**Carryall 1, Carryall Turf 1
FD/FG/HD/HG
1137-227446 to 1139-233202**



**Carryall 2, Carryall 2 Plus,
Turf 2, Turf 2 Plus
EG/PG/QB/QT/RG
1137-227426 to 1139-233129**



**Carryall 6, Carryall Turf 6
JR/JU/JV
1137-227518 to 1139-232421**



**XRT 800, 810, 850, 900
AE/JM/JY/JZ/XF/XJ
1137-227641 to 1139-232482**



**Carryall 252, Turf 252
JK/JL/XG/ZG
1137-227376 to 1139-232478**