



August 2010

URGENT SAFETY RECALL

CLUB CAR MODEL YEAR 2010 DS GOLF CARS, HOSPITALITY AND UTILITY & TRANSPORT VEHICLES

Dear Club Car Customer:

Club Car, LLC, in cooperation with the U. S. Consumer Product Safety Commission, is notifying all owners and operators of 2010 model year DS golf cars and small wheeled utility products of a risk of brake pedal breakage in certain units due to a missing weld. This problem, if not corrected, could present a potential risk of unexpected loss of braking and potential injury; thus, Club Car is undertaking a voluntary inspection of the brake pedal assemblies with certain manufacturing date codes in 2010 model year vehicles to insure the weld is present.

Club Car, in conjunction with its dealers and distributors, has initiated a field campaign to inspect the brake pedal assemblies in the affected vehicles. The inspection will be done free of charge. If it is discovered that a weld is missing, the brake pedal will be replaced free of charge.

This letter is to provide the information you will need to identify the affected vehicles and the actions you should take to ensure that brake pedal assembly in your vehicle is inspected expeditiously.

Which vehicles are affected?

- Certain 2010 DS model golf cars, hospitality, utility & transport and rough terrain vehicles. A full listing of affected models and serial numbers is attached. Precedent model golf cars and All Wheel Drive products **are not** affected.

What is the problem?

- A very small number of brakes pedals may be missing a weld.
- This condition, if uncorrected, may lead to loss of brakes on the vehicle.

Our records indicate that you are the current owner of a 2010 DS model golf car, hospitality, or utility & transport vehicle or vehicles. If you are no longer in possession of the vehicle(s), please contact us at 1-800-227-0739 extension 3580 with any information you might have concerning their current location.

Immediate actions to be taken for affected vehicles:

STEP 1:

- Determine whether the serial number(s) of your 2010 DS model golf car, hospitality, or utility & transport vehicle or vehicles are on the list of potentially affected vehicles in Table 1 (see serial number decal example at right). The serial number is located on a decal just above and to the right of the accelerator pedal. The serial number consists of a two-letter prefix followed by a ten-digit number. The prefix and number must both match the model listings shown below for your vehicle to be affected.



STEP 2

- If your vehicle is included in Table 1, **STOP USING THE VEHICLE** and immediately contact your authorized Club Car dealer or call Club Car at **1-800-227-0739, ext. 3580** between 8 a.m. and 5 p.m. ET to arrange for an inspection of your vehicle(s).

We have initiated these steps out of our concern for safety and continued satisfaction with Club Car products and regret any inconvenience this may cause. Your cooperation and patience in dealing with this important issue is appreciated.

TABLE 1

Golf Cars and Hospitality Vehicles



**DS Electric Golf Car
IQ System / PowerDrive System 48
AQ
1042-139425 to 1051-160548**



**DS Gas Golf Car
AG
1042-139271 to 1054-160914**



**Café Express,
AF
1039-133641 to 1051-159858**

Transportation and Utility Vehicles



**Villager 4
FQ/TG
1044-143850 to 1050-157489**



**Villager 6, Villager 6 Plus
KG/QS
1040-133698 to 1054-160812**



**Villager 8
MG/QE
1040-133677 to 1051-159571**



**Carryall 232
XL/XM
1044-143891 to 1054-160925**



**TransPorter 4
JS/JT/N/NG
1040-134403 to 1054-160949**



**TransPorter 6
JP/JQ
1041-136942 to 1050-158272**



**Carryall 1, Carryall Turf 1
FD/FG/HD/HG
1042-139249 to 1054-160814**



**Carryall 2, Carryall 2 Plus,
Turf 2, Turf 2 Plus
EG/PG/QB/QT/RG
1040-133683 to 1054-161253**



**Carryall 6, Carryall Turf 6
JR/JU/JV/N/NG
1040-133932 to 1054-161146**



**XRT 800, 810, 850, 900
AE/JM/JY/JZ/XE/XF/XH/XJ/XU
1042-140353 to 1054-160961**



**Carryall 252, Turf 252
JK/JL/XG/ZG
1040-133693 to 1051-159981**

Custom Vehicles

**CQ
1044-143845 to 1044-143847**